


Doc.No. 5207-005000A Date: 200617 Approved by: PL

Change No. 19909





To make the security test the tablestand need to be removed. That is easily done by just loosen the screws.


Date: 200617

Doc.No. 5207-005000A

Change No. 19909

Approved by: PL






Doc.No. 5207-005000A Date: 200617 Approved by: PL

Change No. 19909





Risk for oil leakage in the quick coupling, see the area the arrow shows. It's is very important that the Ergo pipe is not loosen and it has it's original position to prevent sudden oil leakage.

Doc.No. 5207-005000A Date: 200617 Approved by: PL

Change No. 19909